Are You Covered?

Dear Half-Mast,

The cover on my Paladin's engine impeller fan is dinged and banged up to the point that the fan vibrates too much. I've looked in the parts TM, but can't find a replacement cover.

It seems a shame to order a new fan just because of a bad cover. Should I try to find one through my cannibalization point?

SGT J.W.C.

Dear Sergeant J.W.C.,

The fan cover is not stocked because impeller fans are high-speed balanced at the factory with the covers in place. Exchanging a damaged cover for another one will result in an unbalanced fan that will vibrate enough to eventually fail.

Always replace the entire fan, NSN 4140-01-284-5722, whenever the cover is damaged enough to cause noise or excessive vibration.

Cover damaged? Replace engine impeller fan



PS 577 17 DEC 00